

XV50, XV144, XV222 ASSEMBLY MANUAL ERRATA

Rev. B-1, August 7, 2006

**THESE MANUAL CORRECTIONS MUST BE MADE
TO THE ASSEMBLY MANUAL OR YOUR
TRANSVERTER MAY NOT FUNCTION CORRECTLY**

- 1. Page 9, Inventory list, Part Reference “F1”:** Change the Elecraft Part Number for F1 from E980065 to E980113. Change the description to “Resettable Fuse, 8 Ampere, 16 Volt”.